

Closure Checklist

Closure Type: Wellhead Closure

Site Name: Binder 9-28

Remediation #:: 42825

Latitude, Longitude:: 40.369383, -104.889911

General Condition of Good Site:

USCS Soil Type: SC - Sands with fines - sand/clay mixture

Estimated Depth of Groundwater **more than 20' bgs**

Potential Hydrocarbon Impacted Soils/Spills **None Observed**

Salt Crusted Soils or Impacted Vegetation **None Observed**

Soil Samples

#	Date	Time	Sample ID	PID	Visual	Olfactory	Equipment	Lab
1	01/09/2026	11:45	WH-B01@6'	2.2	No Staining	No odor	Wellhead	Yes

1 - P1



Facing north

Was impacted soil identified?: No

Total number of soil samples field screened: 17

Total number of soil samples collected: 17

Highest PID reading: 2.2

Total number of soil samples submitted for analysis: 9

Was groundwater encountered during the investigation **No**

Measured Depth to Groundwater:

Was remedial groundwater removal conducted?

Date groundwater was encountered:

Commencement date of removal:

Sheen on groundwater?

Free product observed?

Volume of groundwater removed prior to sampling:

Volume of groundwater removed post sampling:

Total volume of groundwater removed:

Total volume of groundwater samples collected:

Total volume of groundwater samples submitted to lab for analysis:

Signature

