

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
404416771
Receive Date:
11/26/2025

Report taken by:
Abdul Elnajdi

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: NOBLE ENERGY INC	Operator No: 100322	Phone Numbers
Address: 1099 18TH STREET SUITE 1500		Phone: (970) 304-5000
City: DENVER State: CO Zip: 80202		Mobile: ()
Contact Person: Dan Peterson	Email: RBUEUF27@chevron.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 25396 Initial Form 27 Document #: 403169076

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

No Multiple Facilities

Facility Type: LOCATION	Facility ID: 465071	API #: _____	County Name: WELD
Facility Name: PATRIOT B-65N64W 16SESE	Latitude: 40.395658	Longitude: -104.550191	
	** correct Lat/Long if needed: Latitude: 40.395839	Longitude: -104.550681	
QtrQtr: SESE	Sec: 16	Twtp: 5N	Range: 64W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications SW Most Sensitive Adjacent Land Use Crop Land
Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? Yes
Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

Riverine 0.19mi W
Freshwater Pond 0.25mi NW
HWY 0.22mi S
Freshwater Emergent Wetlands 0.24mi S
No other potential receptors are located within 1/4 mile of the Site.
Above distances are approximations.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- E&P Waste** **Other E&P Waste** **Non-E&P Waste**
- Produced Water** **Workover Fluids** _____
- Oil** **Tank Bottoms**
- Condensate** **Pigging Waste**
- Drilling Fluids** **Rig Wash**
- Drill Cuttings** **Spent Filters**
- Pit Bottoms**
- Other (as described by EPA)** _____

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	GROUNDWATER	NA	Field Screening and Lab Analysis if encountered
Yes	SOILS	Refer to Tables and Figures	Field Screening and Lab Analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

A site investigation was conducted pursuant to ECMC Rule 911 at the PATRIOT T5N-R64W-S16 L02 Tank Battery location.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Grab confirmation soil samples were collected from the produced water vessel(s) excavation, beneath the ground oil tank(s), and at the separator(s). Soil samples were analyzed by a certified laboratory for TPH (total volatile [C6-C10] and extractable [C10-C36] hydrocarbons), organic compounds in soil per ECMC Table 915-1, and EC, SAR, pH, and boron. All samples collected will be analyzed by a certified laboratory using approved ECMC laboratory analysis methods.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

If groundwater is encountered during additional site assessment activities, a grab groundwater sample will be collected and analyzed for all organic compounds and inorganic parameters per Table 915-1.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Visual inspection of the tank battery area occurred during abandonment activities. Field personnel field screened all disturbed areas using a PID, visual, and olfactory senses to determine if laboratory confirmation sampling was required. The ECMC Tank Battery and Produced Water Vessel Closure Checklists were utilized and filled out during the abandonment process. A photolog was attached.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 12
Number of soil samples exceeding 915-1 5
Was the areal and vertical extent of soil contamination delineated? No
Approximate areal extent (square feet) 500

NA / ND

ND Highest concentration of TPH (mg/kg) _____
-- Highest concentration of SAR 1.83
BTEX > 915-1 No
Vertical Extent > 915-1 (in feet) 3

Groundwater

Number of groundwater samples collected 0
Was extent of groundwater contaminated delineated? Yes
Depth to groundwater (below ground surface, in feet) _____
Number of groundwater monitoring wells installed _____
Number of groundwater samples exceeding 915-1 _____

Highest concentration of Benzene (µg/l) _____
Highest concentration of Toluene (µg/l) _____
Highest concentration of Ethylbenzene (µg/l) _____
Highest concentration of Xylene (µg/l) _____
Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected
 Number of surface water samples exceeding 915-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Twenty-one background soil samples were collected from an area not impacted by oil and gas development, at depths and within lithologies comparable to the confirmation soil samples collected at the site. These samples were analyzed for Table 915-1 metals and SSR constituents. Analytical results for the background samples indicated elevated levels of pH, SAR, and several metals, including Arsenic (As), Barium (Ba), Cadmium (Cd), Copper (Cu), Lead (Pb), Nickel (Ni), Selenium (Se), and Silver (Ag).

Background Soil Sample Analysis (mg/kg)
Total pH: Max = 8.52
Total SAR: Max = 10.9
Total As: Max*1.25 = 19.1
Total Ba: Max*1.25 = 428
Total Cd: Max*1.25 = 2.20
Total Cu: Max*1.25 = 78.9
Total Pb: Max*1.25 = 178.8
Total Ni: Max*1.25 = 63.9
Total Se: Max*1.25 = 0.949
Total Ag: Max*1.25 = 1.24

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____ Volume of liquid waste (barrels) _____

Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? Yes

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

The organic compound exceedances observed at sample location SEP01 0.5ft (2) will be removed through a remedial excavation. Remedial excavation confirmation soil samples will be collected and analyzed for full ECMC Table 915-1 constituents. The impacted soil will be disposed of at an approved landfill as non-hazardous waste in accordance with Rules 905 and 906. Copies of the waste manifests will be available upon request.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Laboratory analytical results indicated a historical release had occurred at the location of soil sample SEP01 0.5ft (2) and was reported as a historic release in Form 19 document number 404417861.

The source will be excavated and confirmation soil samples will be collected and analyzed for the full Table 915-1 suite of analytes.

If groundwater is encountered during the excavation of impacted soil, a groundwater sample will be collected for Table 915-1 organic and inorganic constituents in groundwater (Benzene, Toluene, Ethylbenzene, Total Xylenes (BTEX), naphthalene, 1,2,4-Trimethylbenzene, 1,3,5-Trimethylbenzene, Chloride ion, Sulfate ion and Total Dissolved Solids (TDS). Should no additional active remediation be required following source removal at the location, a no further action (NFA) determination will be requested within 90 days following laboratory confirmation of the removal of impacted soils with respect to the applicable Table 915-1 screening levels at the site.

If groundwater impacts are observed, an NFA will be requested once four consecutive quarters of groundwater sampling have been completed and reported at the location with concentrations of Table 915-1 constituents below regulatory limits. As needed, soil and/or groundwater remediation plans will be developed and submitted to ECMC in a supplemental Form 27.

Soil Remediation Summary

In Situ

Ex Situ

_____ Bioremediation (or enhanced bioremediation)

_____ Excavate and offsite disposal

_____ Chemical oxidation

_____ If Yes: Estimated Volume (Cubic Yards) _____

_____ Air sparge / Soil vapor extraction

_____ Name of Licensed Disposal Facility or ECMC Facility ID # _____

_____ Natural Attenuation

_____ Excavate and onsite remediation

_____ Other _____

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

If groundwater is encountered during additional site assessment activities, a grab groundwater sample will be collected and analyzed for all organic compounds and inorganic parameters per Table 915-1.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

Quarterly Semi-Annually Annually Other

Request Alternative Reporting Schedule:

Semi-Annually Annually Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report

Other Supplemental Site Investigation Results Submittal & Source Mass Removal Proposal _____

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policies MWZZ316714 and MWZX316724) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.

Operator anticipates the remaining cost for this project to be: \$ 50000 _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? No

Does the previous reply indicate consideration of background concentrations? _____

Does Groundwater meet Table 915-1 standards? Yes

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? Yes

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 10/31/2025

Proposed date of completion of Reclamation. 06/30/2027

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 07/21/2022

Actual Spill or Release date, or date of discovery. 10/20/2025

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 01/16/2023

Proposed site investigation commencement. 09/25/2022

Proposed completion of site investigation. 10/02/2025

REMEDIAL ACTION DATES

Proposed start date of Remediation. 10/02/2025

Proposed date of completion of Remediation. 06/30/2026

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

The 'Proposed completion of site investigation' section has been updated with the actual date supplemental site investigation activities were completed. The 'Proposed date of completion of Remediation' section has been updated to reflect the need for impacted source mass removal at sample location SEP01 0.5ft (2). Remedial excavation activities will be completed following approval of this supplemental form 27.

OPERATOR COMMENT

This Form 27 is being submitted as a Q4 2025 timeline update for the former Patriot B-65N64W 16SESE tank battery location. The submittal includes 10/2/2025 supplemental site investigation results and proposes a source mass removal.

On 10/2/2025, PATRIOT B-65N64W 16SESE tank battery re-sampling activities were completed. During the completion of the activities, no potential presence of impacted material(s) was observed/smelled. Consistent with Rule 912, samples were collected and analyzed to determine whether any constituents are present at levels in excess of Table 915-1 standards. Final laboratory analytical results received on 10/20/2025 indicated that soil sample, SEP01 0.5ft (2), discovered at the former separator, exceeded ECMC Table 915 standards for benzo(a)anthracene at 0.038 mg/kg. Groundwater was not encountered during decommissioning activities.

This form also documents that the spill associated with Form 19 (Document No. 404417861) will be remediated as outline in the remedial action plan section of this Form 27 (Rule 912.c; Remediation No. 25396). Document number 404417861 remains in process at the time of this submittal; a spill ID will be added to the subsequent Form 27 pending its approval. Pending site access, landowner approval, and crew availability, the operator will complete the excavation activities as outlined in this proposed Remedial Action Workplan.

Furthermore, the Operator proposes to conduct a Wilcoxon statistical analysis comparing flowline and wellhead confirmation samples to background samples. The objective of this analysis is to demonstrate that site sample concentrations reflect naturally occurring background levels of ECMC Table 915-1 metals, with particular emphasis on copper.

Based on currently available data, this project is not affected by data integrity irregularities and is not associated with the operator's data integrity review process and its Rule 525.e. Voluntary Disclosure. As part of its data integrity review process, the operator requested the lab protect the laboratory analytical reports from subsequent unauthorized modification by anyone outside the lab, which resulted in the lab reissuing the original reports with additional protections (Reissued Reports). The Reissued Reports were received directly from the lab on March 29, and April 4, 2025, which the application of a Digital ID/Verified Certification (lock) to support reissuance. The metadata associated with this Reissued Reports also includes the lab representative's name, the date and time the laboratory reissued the reports, and an explanation for the reports reissuance. The Reissued Reports are attached to this submission.

In the event additional responsive information is received or discovered that would suggest this project should be incorporated into the ongoing data integrity review process associated with Operator's Rule 525.e. Voluntary Disclosure, Operator will update and/or amend the statements in this submission and provide any new or revised data or other information.

Quarterly reporting will be conducted until closure criteria are achieved for the remediation project. The results of the supplemental site investigation will be submitted on a subsequent Form 27.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Jeff Griggs

Title: Consultant

Submit Date: 11/26/2025

Email: jeffg@fremontenv.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Abdul Elnajdi

Date: 01/23/2026

Remediation Project Number: 25396

COA Type

Description

COA Type	Description
0 COA	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

404416771	FORM 27-SUPPLEMENTAL-SUBMITTED
404448256	LABORATORY ANALYTICAL REPORT
404448257	LABORATORY ANALYTICAL REPORT
404448259	LABORATORY ANALYTICAL REPORT
404448261	LABORATORY ANALYTICAL REPORT
404448264	SITE INVESTIGATION REPORT
404448266	REMEDIAL ACTION PLAN

Total Attach: 7 Files

General Comments

User Group

Comment

Comment Date

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)