

Inspection Photos

API: 071-09073

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 1/22/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west along the access road. There were recent repairs at the drainage crossing. Additional BMP's have been installed in this area.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09073 | Date: 1/22/2026

Inspection Photos



Photo 2. Facing southeast toward the wellsite.



Inspection Photos



Photo 3. There is a sediment tap at the northeast corner that is maintained..



Inspection Photos



Photo 4. Facing south along the fill slope.

