

Inspection Photos

API: 071-08758

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 1/22/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west along the access road. There is an area of erosion shown at red arrow.



Inspection Photos



Photo 2. This area of erosion along the roadside will need to be repaired and stabilized..



Inspection Photos



Photo 2. Facing northeast toward the wellsite.

