

Inspection Photos

API: 071-06187

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 1/22/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the main access road which is east of the wellsite. There is erosion along the road and the roadside is not stabilized.



Inspection Photos



Photo 2. The culvert shown at red arrow has filled in with sediment...



Inspection Photos



Photo 3. The culvert shown at red arrow has filled in with sediment...



Inspection Photos



Photo 4. Facing southwest toward the wellsite.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06187 | Date: 1/22/2026