

# Inspection Photos

1/16/2026

**Operator:** TEP ROCKY MOUNTAIN LLC 96850

**Location ID:** 315513

**Inspection Doc:** 718101066

Rio Blanco County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC 96850

Location ID: 315513



**Photo 1:** Photos 1-2 taken from the northwest end of the working pad surface. Photos provide an overview of the Location from northeast, east, south to southwest. Interim reclamation pursuant to Rule 1003 has been performed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC 96850

Location ID: 315513



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC 96850

Location ID: 315513



**Photo 3:** Photos taken from the northern edge of the working pad surface, facing north and northeast. Photo shows the cuttings trench area has been backfilled and surface reclaimed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC 96850

Location ID: 315513



**Photo 4:** Photos taken from the NW edge of the working pad surface. Photos show point where stormwater runoff from the WPS is discharging onto the interim areas of the Location. Stormwater and erosion control BMPs to manage runoff in a manner that minimizes erosion degradation and sediment transport were not observed, and erosion degradation issues are becoming apparent.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC 96850

Location ID: 315513



**Photo 5:** Photo taken from the northwest end of the Location. Photo shows unmarked anchor.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC 96850

Location ID: 315513



**Photo 6:** Photos taken from the northeast end of the Location. Photos 6-10 examples of various trash, debris and/or unused equipment observed improperly stored on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC 96850

Location ID: 315513



**Photo 7:** See comments under photo 6.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC 96850  
Location ID: 315513



**Photo 8:** See comments under photo 6.



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC 96850  
Location ID: 315513



**Photo 9:** See comments under photo 6.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC 96850

Location ID: 315513



Photo 10: See comments under photo 6.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC 96850

Location ID: 315513



**Photo 11:** Photos 11-13 examples showing spills/strained soils observed throughout the working pad surface of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC 96850

Location ID: 315513



**Photo 12:** See comments under photo 11.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC 96850

Location ID: 315513



**Photo 13:** See comments under photo 11.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC 96850  
Location ID: 315513



**Photo 14:** Loadline missing cap/plug.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC 96850

Location ID: 315513



**Photo 15:** Photo taken from the interim slopes on the south end of the Location, facing southwest. Photo shows dense infestation of undesirable plant species. Weed debris requires removal and proper disposal. Additional and ongoing weed management efforts required.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources