

Final Reclamation Inspection

January 2, 2026

Operator: NOBLE ENERGY INC - 100322

Location ID: 419040

Inspection Document #: 718801229

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Hoff PC D06-22D Tank

Location ID: 419040



Photo 1. Photo taken of the tank battery location, facing northwest. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. Fencing is in place surrounding the location.



Photo 2. Photo taken of the tank battery location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: Hoff PC D06-22D Tank
Location ID: 419040



Photo 3. Photo taken of the tank battery location, facing south.
See comments under Photo 1.



Photo 4. Photo taken of the tank battery location, facing east.
See comments under Photo 1.

Inspection Photos

Location Name: Hoff PC D06-22D Tank

Location ID: 419040



Photo 5. Photo taken of ground cover at the tank battery location.



Photo 6. Photo taken of the reference area to the location, east of the location, facing northeast. Photo illustrates perennial grass and sand sagebrush.

