

Final Reclamation Inspection

January 2, 2026

Operator: NOBLE ENERGY INC - 100322

Location ID: 328268

Inspection Document #: 718801239

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MCKENNEY #6-14
Location ID: 328268



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards. Fencing is in place surrounding the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: MCKENNEY #6-14
Location ID: 328268



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: MCKENNEY #6-14
Location ID: 328268



Photo 5. Photo taken of ground cover at the well location. Photo illustrates bare ground and perennial grass with evidence of drill rows from seeding.



Photo 6. Photo taken of the access road to the well location, facing northwest. Photo illustrates that bare ground remains.



Inspection Photos
Location Name: MCKENNEY #6-14
Location ID: 328268



Photo 7. Photo taken of the reference area to the well location, west of the location, facing west. Photo illustrates perennial grass vegetation.