

Final Reclamation Inspection

January 2, 2026

Operator: PDC ENERGY INC - 69175

Location ID: 327533

Inspection Document #: 718801241

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MCKENNEY #6-3
Location ID: 327533



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: MCKENNEY #6-3
Location ID: 327533



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: MCKENNEY #6-3
Location ID: 327533



Photo 5. Photo taken of the tank battery location, facing northwest. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation has not established to Rule 1004 standards.



Photo 6. Photo taken of the tank battery location, facing west. See comments under Photo 5.

Inspection Photos
Location Name: MCKENNEY #6-3
Location ID: 327533



Photo 7. Photo taken of the tank battery location, facing east. See comments under Photo 5.



Photo 8. Photo taken of the reference area to the location, south of the location, facing south. Photo illustrates perennial grass vegetation.