

Final Reclamation Inspection

January 2, 2026

Operator: PDC ENERGY INC - 69175

Location ID: 327836

Inspection Document #: 718801245

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MCKENNEY #6-42
Location ID: 327836



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards. Fencing is in place surrounding the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: MCKENNEY #6-42
Location ID: 327836



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: MCKENNEY #6-42
Location ID: 327836



Photo 5. Photo taken of the access road to the well location, facing west. Photo illustrates that final reclamation along the access road does not meet Rule 1004 standards.



Photo 6. Photo taken of the reference area to the location, northwest of the location, facing northeast. Photo illustrates perennial grass vegetation.

