

Final Reclamation Inspection

January 2, 2026

Operator: PDC ENERGY INC - 69175

Location ID: 310152

Inspection Document #: 718801243

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MCKENNEY #5
Location ID: 310152



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: MCKENNEY #5
Location ID: 310152



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: MCKENNEY #5
Location ID: 310152



Photo 5. Photo taken of the tank battery location, facing northeast. See comments under Photo 1.



Photo 6. Photo taken of the access road to the well location, facing southwest. Photo illustrates that final reclamation activities do not appear to taken place along the access road as bare ground remains.

Inspection Photos
Location Name: MCKENNEY #5
Location ID: 310152



Photo 7. Photo taken of the access road to the well location, facing southwest. Photo illustrates that the access road remains unreclaimed with a cattle guard that is no longer in proper working condition.



Photo 8. Photo taken of the access road to the location, facing northeast. See comments under Photo 7.

Inspection Photos
Location Name: MCKENNEY #5
Location ID: 310152



Photo 9. Photo taken of the reference area to the location, north of the location, facing west. Photo illustrates perennial grass vegetation.