

# Final Reclamation Inspection

January 2, 2026

Operator: NOBLE ENERGY INC - 100322

Location ID: 328267

Inspection Document #: 718801231

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: MCKENNEY #6-12  
Location ID: 328267



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos  
Location Name: MCKENNEY #6-12  
Location ID: 328267



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos  
Location Name: MCKENNEY #6-12  
Location ID: 328267



**Photo 5.** Photo taken of the well location, facing west. Photo illustrates fencing surrounds the well site.



**Photo 6.** Photo taken of the access road the location, facing northeast. Photo illustrates that final reclamation does not meet Rule 1004 standards along the access road.

Inspection Photos  
Location Name: MCKENNEY #6-12  
Location ID: 328267



**Photo 7.** Photo taken of ground cover at the well location. Photo illustrates perennial grass vegetation which has not yet established to Rule 1004 standards.



**Photo 8.** Photo taken of the reference area to the well location, south of the location, facing south. Photo illustrates perennial grass vegetation.

