

Final Reclamation Inspection

January 2, 2026

Operator: PDC ENERGY INC - 69175

Location ID: 306543

Inspection Document #: 718801261

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BECKER #6-111
Location ID: 306543



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: BECKER #6-111
Location ID: 306543



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: BECKER #6-111
Location ID: 306543



Photo 5. Photo taken of ground cover at the location. Photo illustrates perennial grass, bare ground, and drill rows from seeding.



Photo 6. Photo taken of the tank battery location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards.

Inspection Photos
Location Name: BECKER #6-11I
Location ID: 306543



Photo 7. Photo taken of the tank battery location, facing west. See comments under Photo 6.



Photo 8. Photo taken of the tank battery location, facing east. See comments under Photo 6.

Inspection Photos
Location Name: BECKER #6-11I
Location ID: 306543



Photo 9. Photo taken of the tank battery location, facing southeast. See comments under Photo 6.



Photo 10. Photo taken of the reference area to the location, west of the location, facing west. Photo illustrates perennial grass and weedy annual vegetation.