

# Final Reclamation Inspection

January 2, 2026

Operator: PDC ENERGY INC - 69175

Location ID: 329181

Inspection Document #: 718801253

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: BECKER #5-10  
Location ID: 329181



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos  
Location Name: BECKER #5-10  
Location ID: 329181



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos  
Location Name: BECKER #5-10  
Location ID: 329181



**Photo 5.** Photo taken of ground cover at the location. Photo illustrates perennial grass, bare ground, and drill rows from seeding.



**Photo 6.** Photo taken of the reference area to the location, north of the location, facing northeast. Photo illustrates perennial grass and weedy annual vegetation.