

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT GM 41-29 Pad

Location ID: 335075



Photo # 3590 From entrance to location

Photo # 3591 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT GM 41-29 Pad

Location ID: 335075



Photo # 3592 Location



Photo # 3593 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT GM 41-29 Pad

Location ID: 335075



Photo # 3594 Location



Photo # 3595 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT GM 41-29 Pad

Location ID: 335075



Photo # 3596 Location



Photo # 3597 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT GM 41-29 Pad

Location ID: 335075




Photo # 3598 Open ended load line

Photo # 3599 Open ended load line