

Inspection Photos

01/22/2026

Operator: TEP Rocky Mountain LLC #96850

Location ID: 324180

Inspection Doc: 719200708

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324180



Photo 1: Photos showing and overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324180



Photo 2: Photos showing and overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324180



Photo 3: Photos showing the western and southern stormwater controls appear to have been implemented/maintained. These Corrective Actions from inspection #719200427 has been resolved.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324180



Photo 4: Photos showing erosion and rilling on the perimeter of the eastern interim area. Stormwater BMP's appear to be missing or insufficient; maintenance is required. The Corrective Action from inspection # 719200427 remains outstanding.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources