

Inspection/Audit Photos

Location: KT RESOURCES LLC WRD UNIT #29-12 PAD

Location ID: 316208

Date: 01/6/2026



Photo # 0757 Entrance to location

Photo # 0769 Location

Inspection/Audit Photos

Location: KT RESOURCES LLC WRD UNIT #29-12 PAD

Location ID: 316208

Date: 01/6/2026



Photo # 0758 Location



Photo # 0762 Location

Inspection/Audit Photos

Location: KT RESOURCES LLC WRD UNIT #29-12 PAD

Location ID: 316208

Date: 01/6/2026



Photo # 0768 Location



Photo # 0793 SE corner of location

Inspection/Audit Photos

Location: KT RESOURCES LLC WRD UNIT #29-12 PAD

Location ID: 316208

Date: 01/6/2026



Photo # 0794 NE corner of location



Photo # 0795 NW corner of location

Inspection/Audit Photos

Location: KT RESOURCES LLC WRD UNIT #29-12 PAD

Location ID: 316208

Date: 01/6/2026



Photo # 0796 SW corner of location

Photo # 0779 Weeds & weed debris in secondary containment presents a potential fire hazard

Inspection/Audit Photos

Location: KT RESOURCES LLC WRD UNIT #29-12 PAD

Location ID: 316208

Date: 01/6/2026



Photo # 0781 Weeds & weed debris in secondary containment presents a potential fire hazard

Photo # 0784 Weeds & weed debris in secondary containment presents a potential fire hazard

Inspection/Audit Photos

Location: KT RESOURCES LLC WRD UNIT #29-12 PAD

Location ID: 316208

Date: 01/6/2026



Photo # 0785 Weeds & weed debris in secondary containment presents a potential fire hazard

Photo # 0787 Weeds & weed debris in secondary containment presents a potential fire hazard

Inspection/Audit Photos

Location: KT RESOURCES LLC WRD UNIT #29-12 PAD

Location ID: 316208

Date: 01/6/2026




Photo # 0788 Weeds & weed debris in secondary containment presents a potential fire hazard



Photo # 0797 1 Improperly marked deadman on west side of location

Inspection/Audit Photos

Location: KT RESOURCES LLC WRD UNIT #29-12 PAD

Location ID: 316208

Date: 01/6/2026



Photo # 0802 Subsidence on NW side of location

Photo # 0803 Subsidence on NW side of location