

Final Reclamation Inspection

October 7th, 2025

Operator: Kerr McGee Oil & Gas Onshore - 47120

Location ID: 329651

Inspection Document #: 714003384

Weld County, CO

Corey Mcdonough
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 1. NAIP aerial imagery (2009) illustrating the well location (red circle) and associated tank battery location (blue polygon). The tank battery is associated with location ID #319193.



Photo 2. Orthomosaic (drone) imagery taken 10/7/2025 and NAIP imagery (2023) illustrating the well location (red circle) and associated tank battery (blue polygon).

Inspection Photos

Location Name: MARRS Red VV 22-4

Location ID: 329651



Photo 3. Drone aerial imagery taken south of well location, facing north (displaying the well).





Photo 4. Drone aerial imagery taken west of well location, facing east (displaying the well and flowline).

Inspection Photos

Location Name: Marrs Red VV 22-4

Location ID: 329651



Photo 5. Drone aerial imagery taken north of well location, facing south (displaying the well).



Inspection Photos

Location Name: Marris Red VV 22-4

Location ID: 329651



Photo 6. Drone aerial imagery taken east of well location, facing west (displaying the well).

