

Final Reclamation Inspection

January 6, 2026

Operator: PDC ENERGY INC - 69175

Location ID: 305170

Inspection Document #: 718801275

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BECKER #6
Location ID: 305170



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including russian thistle (*Salsola tragus*) was observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: BECKER #6
Location ID: 305170



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: BECKER #6
Location ID: 305170



Photo 5. Photo taken of ground cover at the location. Photo illustrates weedy annual vegetation including russian thistle (*Salsola tragus*).



Photo 6. Photo taken of the reference area to the location, south of the location, facing south.

