

Final Reclamation Inspection

January 6, 2026

Operator: PDC ENERGY INC - 69175

Location ID: 322943

Inspection Document #: 718801273

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BECKER #5-1
Location ID: 322943



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: BECKER #5-1
Location ID: 322943



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: BECKER #5-1
Location ID: 322943



Photo 5. Photo taken of ground cover at the location. Photo illustrates bare ground and perennial grass.



Photo 6. Photo taken of the tank battery location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation has not established to Rule 1004 standards.

Inspection Photos
Location Name: BECKER #5-1
Location ID: 322943



Photo 7. Photo taken of the tank battery location, facing west. See comments under Photo 6.



Photo 8. Photo taken of the tank battery location, facing southwest. See comments under Photo 6.



Inspection Photos
Location Name: BECKER #5-1
Location ID: 322943



Photo 9. Photo taken of the reference area to the location, east of the location, facing south. Photo illustrates perennial grass and sand sagebrush.

