

Final Reclamation Inspection

January 6, 2026

Operator: PDC ENERGY INC - 69175

Location ID: 329407

Inspection Document #: 718801265

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BECKER #5-12
Location ID: 329407



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: BECKER #5-12
Location ID: 329407



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: BECKER #5-12
Location ID: 329407



Photo 5. Photo taken of ground cover at the location. Photo illustrates perennial grass and bare ground.



Photo 6. Photo taken of the tank battery location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation has not established to Rule 1004 standards and bare ground was observed across the location.

Inspection Photos
Location Name: BECKER #5-12
Location ID: 329407



Photo 7. Photo taken of the tank battery location, facing west. See comments under Photo 6.



Photo 8. Photo taken of the tank battery location, facing west. See comments under Photo 6.

Inspection Photos
Location Name: BECKER #5-12
Location ID: 329407



Photo 9. Photo taken of the reference area to the location, east of the location, facing east. Photo illustrates perennial grass, sand sagebrush, and weedy annual vegetation.