

Final Reclamation Inspection

January 6, 2026

Operator: NOBLE ENERGY INC - 100322

Location ID: 306117

Inspection Document #: 718801289

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Dietrich C #06-23
Location ID: 306117



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards and weedy annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: Dietrich C #06-23
Location ID: 306117



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: Dietrich C #06-23
Location ID: 306117




Photo 5. Photo taken of ground cover at the well location. Photo illustrates perennial grass and weedy annual vegetation including kochia (*Bassia scoparia*).



Photo 6. Photo taken of the access road to the location, facing west. Photo illustrates that final reclamation activities appear to have taken place along the road, but vegetation has not established to Rule 1004 standards.

Inspection Photos
Location Name: Dietrich C #06-23
Location ID: 306117



Photo 7. Photo taken of the reference area to the location, southwest of the location, facing south. Photo illustrates perennial grass vegetation.