

Final Reclamation Inspection

January 6, 2026

Operator: NOBLE ENERGY INC - 100322

Location ID: 330872

Inspection Document #: 718801293

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DINNER #6-34
Location ID: 330872



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including russian thistle (*Salsola tragus*) and kochia (*Bassia scoparia*) were observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: DINNER #6-34
Location ID: 330872



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: DINNER #6-34
Location ID: 330872



Photo 5. Photo taken of ground cover at the well location. Photo illustrates weedy annual vegetation including russian thistle (*Salsola tragus*) and kochia (*Bassia scoparia*).



Photo 6. Photo taken of the access road to the location, facing north. Photo illustrates that bare ground and weedy annual vegetation, including russian thistle (*Salsola tragus*) and kochia (*Bassia scoparia*), were observed across the road.



Inspection Photos
Location Name: DINNER #6-34
Location ID: 330872



Photo 7. Photo taken of the reference area to the location, west of the location, facing west. Photo illustrates perennial grass vegetation.