

Final Reclamation Inspection

January 6, 2026

Operator: NOBLE ENERGY INC - 100322

Location ID: 323527

Inspection Document #: 718801281

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DINNER #6-3
Location ID: 323527



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place and perennial vegetation has established to Rule 1004 standards at the well site.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: DINNER #6-3
Location ID: 323527



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: DINNER #6-3
Location ID: 323527



Photo 5. Photo taken of the tank battery location, facing northeast. Photo illustrates that final reclamation activities have taken place and perennial vegetation has established. However, this location does not meet Rule 1004 standards as field bindweed (*Convolvulus arvensis*), a List C Noxious Weed species, was observed across the tank battery location.



Photo 6. Photo taken of the tank battery location, facing east. See comments under Photo 5.

Inspection Photos
Location Name: DINNER #6-3
Location ID: 323527



Photo 7. Photo taken of the tank battery location, facing northwest. See comments under Photo 5.



Photo 8. Photo taken of ground cover at the tank battery location. Photo illustrates weedy annual vegetation including field bindweed (*Convolvulus arvensis*), a List C Noxious Weed species.



Inspection Photos
Location Name: DINNER #6-3
Location ID: 323527



Photo 9. Photo taken of the reference area to the location, east of the location, facing east. Photo illustrates perennial grass vegetation.

