

# Final Reclamation Inspection

January 6, 2026

Operator: NOBLE ENERGY INC - 100322

Location ID: 329442

Inspection Document #: 718801287

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: DIETRICH #6-10  
Location ID: 329442



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards and weedy annual vegetation including russian thistle (*Salsola tragus*) was observed across the location.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos  
Location Name: DIETRICH #6-10  
Location ID: 329442



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos  
Location Name: DIETRICH #6-10  
Location ID: 329442



**Photo 5.** Photo taken of ground cover at the well location. Photo illustrates weedy annual vegetation including russion thistle (*Salsola tragus*) and kochia (*Bassia scoparia*).



**Photo 6.** Photo taken of the access road to the location, facing south. Photo illustrates that final reclamation activities appear to have taken place along the road, but vegetation has not established to Rule 1004 standards.

Inspection Photos  
Location Name: DIETRICH #6-10  
Location ID: 329442



**Photo 7.** Photo taken of the reference area to the location, south of the location, facing east. Photo illustrates perennial grass vegetation.

