

Final Reclamation Inspection

January 6, 2026

Operator: NOBLE ENERGY INC - 100322

Location ID: 322713

Inspection Document #: 718801291

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LEY #1
Location ID: 322713



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: LEY #1
Location ID: 322713



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: LEY #1
Location ID: 322713



Photo 5. Photo taken of ground cover at the well location. Photo illustrates perennial grass and drill rows from seeding.



Photo 6. Photo taken of the access road to the location, facing south, away from the location. Photo illustrates that final reclamation activities appear to have taken place along the road, but vegetation has not established to Rule 1004 standards.

Inspection Photos
Location Name: LEY #1
Location ID: 322713



Photo 7. Photo taken of the tank battery location, facing east. Photo illustrates that final reclamation activities appear to have taken place at the location, but vegetation has not established to Rule 1004 standards. Weedy annual vegetation including russian thistle (*Salsola tragus*) and kochia (*Bassia scoparia*) was observed across the location.



Photo 8. Photo taken of the tank battery location, facing west. See comments under Photo 7.

Inspection Photos
Location Name: LEY #1
Location ID: 322713



Photo 9. Photo taken of the tank battery location, facing northwest. See comments under Photo 7.



Photo 10. Photo taken of ground cover at the tank battery location. Photo illustrates weedy annual vegetation including kochia (*Bassia scoparia*) and russian thistle (*Salsola tragus*).

Inspection Photos
Location Name: LEY #1
Location ID: 322713



Photo 11. Photo taken of the reference area to the location, west of the well location, facing north. Photo illustrates perennial grass vegetation.

