

Inspection Photos

Location Name: Motu East/2821-8CH

Location #: 439459



Colorado Energy & Carbon Management Commission
Weld County
+40.971193, -104.659775
27° NE
2026-01-22 14:05

Photo #1

Motu East/2821-8CH Tank Battery

Battery / Facility site

Inactive | Shut-down

Equipment Documented; Loc ID: 439459



Colorado Energy & Carbon Management Commission
Weld County
+40.971040, -104.660625
95° E
2026-01-22 13:45

Photo #2

Motu East/2821-8CH Tank Battery

Battery / Facility site

Inactive | Shut-down

Well(site), Battery / Facility entrance



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: Motu East/2821-8CH

Location #: 439459



Photo #3

Motu East/2821-8CH Tank Battery

Battery / Facility site

Inactive | Shut-down

Crude oil, produced H2O tank(s): SE corner



Photo #4

Motu East/2821-8CH Tank Battery

Battery / Facility site

Inactive | Shut-down

*Crude oil, produced H2O tank(s),
recycle pump(s): NW corner*



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Motu East/2821-8CH

Location #: 439459



Photo #5

Motu East/2821-8CH Tank Battery

Battery / Facility site

Inactive | Shut-down

ECD(s); Pilots: OFF, Inactive



Photo #6

Motu East/2821-8CH Tank Battery

Battery / Facility site

Inactive | Shut-down

Treater(s), Separator(s), Line heater(s)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Motu East/2821-8CH

Location #: 439459



Photo #7

Motu East/2821-8CH Tank Battery

Battery / Facility site

Inactive | Shut-down

Bitcoin mining load center(s); Inactive



Photo #8

Motu East/2821-8CH Tank Battery

Battery / Facility site

Inactive | Shut-down

Propane tank(s)

CA: Unmarked container(s)



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: Motu East/2821-8CH

Location #: 439459



Photo #9

Motu East/2821-8CH Tank Battery

Battery / Facility site

Inactive | Shut-down

Electric power bank; Control center



Photo #10

Motu East/2821-8CH Tank Battery

Battery / Facility site

Inactive | Shut-down

Electric power bank; Control center, inside



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Motu East/2821-8CH

Location #: 439459



Photo #11

Motu East/2821-8CH Tank Battery

Battery / Facility site

Inactive | Shut-down

CA: Stained soil

North of treater shed



Photo #12

Motu East/2821-8CH Tank Battery

Battery / Facility site

Inactive | Shut-down

CA: Stained soil

West of power bank shed



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Motu East/2821-8CH

Location #: 439459



Photo #13

Motu East/2821-8CH Tank Battery

Battery / Facility site

Inactive | Shut-down

Treater(s), Separator(s), Line heater(s), recycle pump(s)



Photo #14

Motu East/2821-8CH Tank Battery

Battery / Facility site

Inactive | Shut-down

Treater(s), Separator(s), Line heater(s), recycle pump(s)

CA: Stained soil



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: Motu East/2821-8CH

Location #: 439459



Photo #15

Motu East/2821-8CH Tank Battery

Battery / Facility site

Inactive | Shut-down

Treater(s), Separator(s), Line heater(s), recycle pump(s)

CA: Stained soil



Photo #16

Motu East/2821-8CH Tank Battery

Battery / Facility site

Inactive | Shut-down

Crude oil, produced H2O tank(s): SE corner

CA: Stained soil, trash



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: Motu East/2821-8CH

Location #: 439459



Photo #17

Motu East/2821-8CH Tank Battery

Battery / Facility site

Inactive | Shut-down

Location signage

CA: Invalid Emergency contact number



Photo #18

Motu East/2821-8CH Tank Battery

Battery / Facility site

Inactive | Shut-down

Location tracking pad



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: Motu East/2821-8CH

Location #: 439459

Associated Well(s)	API	Status
<i>Motu East/2821-8CH</i>		LOC # 439459
1. Motu East 28-21-16-1CH	123-40438	SI

Photo #19

Motu East/2821-8CH Tank Battery

Battery / Facility site

Inactive | Shut-down

Associated Well(s): 1

Shut-In | SI



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources