

# Inspection Photos

API: 071-06296

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 1/29/2026

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northeast at the access road. The cattleguard is filled in with sediment and needs to be cleaned out.



## Inspection Photos



**Photo 2.** Facing east toward the wellsite...



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-06296 | Date: 1/29/2026

## Inspection Photos



January 29, 2026  
+37.211937,-104.799567  
Las Animas County  
ECMC

**Photo 3.** Facing southeast toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-06296 | Date: 1/29/2026