

Final Reclamation Inspection

October 8th, 2025

Operator: PDC Energy

Location ID: 329857

Inspection Document #: 714003398

Weld County, CO

Corey Mcdonough
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Booth 13-26
Location ID: 329857




Photo 1. NAIP aerial imagery (2005) illustrating the well location (red circle), associated tank battery location (blue polygon), and access road (black line). The tank battery is associated with location ID #319105.



Inspection Photos
Location Name: Booth 13-26
Location ID: 329857




Photo 2. Orthomosaic (drone) imagery taken 10/8/2025 and NAIP imagery (2023) illustrating the well location (red circle) and associated tank battery (blue polygon).



Photo 3. Drone aerial imagery taken south of well location, facing north (displaying the well).



Photo 4. Drone aerial imagery taken west of well location, facing east (displaying the well).



Photo 5. Drone aerial imagery taken north of well location, facing south (displaying the well, presumed flowline, and access road).





Photo 6. Drone aerial imagery taken east of well location, facing west (displaying the well).



Inspection Photos
Location Name: Booth 13-26
Location ID: 329857



Photo 7. Close-up orthomosaic imagery showing the well location (red circle) and bare patch in field.

