

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH CANYON-FEDERAL #2 PAD

Location ID: 322301

Date: 01/8/2026



Photo # 0850 Entrance to location



Photo # 0873 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH CANYON-FEDERAL #2 PAD

Location ID: 322301

Date: 01/8/2026



Photo # 0852 Location



Photo # 0857 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH CANYON-FEDERAL #2 PAD

Location ID: 322301

Date: 01/8/2026



Photo # 0881 NW corner of location



Photo # 0882 SW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH CANYON-FEDERAL #2 PAD

Location ID: 322301

Date: 01/8/2026



Photo # 0883 SE corner of location



Photo # 0884 NE corner of location