

Inspection Photos

API: 071-09928

Operator: DESERT EAGLE OPERATING LLC

Inspection Date: 1/28/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing south toward the wellsite. The location consists of undesirable which were not controlled. (Darker brown weeds is Russian thistle and Kochia)



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09928 | Date: 1/28/2026

Inspection Photos



Photo 2. Drone aerial photo facing east toward the wellsite. The location consists of undesirable which were not controlled. (Darker brown weeds is Russian thistle and Kochia)



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09928 | Date: 1/28/2026

Inspection Photos



Photo 3. Drone aerial photo facing west along the flowline. Darker brown weeds is Russian thistle and Kochia.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09928 | Date: 1/28/2026

Inspection Photos



Photo 4. Drone aerial photo facing east along the flowline. Darker brown weeds is Russian thistle and Kochia.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09928 | Date: 1/28/2026