

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC Story Gulch Unit/8506D-25 F25496 PAD

Location ID: 415182

Date: 01/15/2026



Jan 15, 2026 at 10:48:31 AM
 +39.674043,-108.120712
 71° E
 81635
 Garfield County
 ECMC



Jan 15, 2026 at 10:59:20 AM
 +39.674682,-108.119023
 48° NE
 81635
 Garfield County
 ECMC

QB Energy Operating, LLC
NORTH PICEANCE
Story Gulch Unit F25 496
UNIT# 496
LEASE# COC74105A

WELL NAME	API#	TOWNSHIP	RANGE	SECTION	QUAD	LAT	LONG
Story Gulch Unit 8084A-25 F25496	0504519156	45	96W	25	NWNE	39.674332	-108.119657
Story Gulch Unit 8084C-25 F25496	0504519080	45	96W	25	NWNE	39.674246	-108.119624
Story Gulch Unit 8084B-25 F25496	0504519078	45	96W	25	NWNE	39.674237	-108.119648
Story Gulch Unit 8085B-25 F25496	0504519130	45	96W	25	SWNW	39.674287	-108.119988
Story Gulch Unit 8085C-25 F25496	0504519084	45	96W	25	SWNW	39.674184	-108.119892
Story Gulch Unit 8086D-25 F25496	0504519087	45	96W	25	SWNW	39.674195	-108.119932
Story Gulch Unit 8086B-25 F25496	0504519167	45	96W	25	SENE	39.674177	-108.119725
Story Gulch Unit 8086C-25 F25496	0504519166	45	96W	25	SENE	39.674271	-108.119725
Story Gulch Unit 8087A-25 F25496	0504519167	45	96W	25	SENE	39.674304	-108.119666
Story Gulch Unit 8087B-25 F25496	0504519068	45	96W	25	SENE	39.674218	-108.119833
Story Gulch Unit 8087C-25 F25496	0504519161	45	96W	25	SENE	39.674311	-108.119642
Story Gulch Unit 8510AX-25 F25	0504519165	45	96W	25	SWNE	39.67426	-108.119749
Story Gulch Unit 8510AX-25 F25	0504519167	45	96W	25	SWNE	39.67423	-108.119809
Story Gulch Unit 8510AX-25 F25	0504519159	45	96W	24	SENE	39.67429	-108.119741
Story Gulch Unit 8510AX-25 F25	0504519162	45	96W	24	SENE	39.674278	-108.119764
SGE 8082E-25 F25496	0504519169	45	96W	24	SWNE	39.674319	-108.119681
SGE 8082E-25 F25496	0504519084	45	96W	24	SENE	39.674482	-108.119412
SGE 8510E-24 F25 49	0504519777	45	96W	25	NWNE	39.674462	-108.119358
SGE 8082E-25 F25496	0504519767	45	96W	24	SWNE	39.674482	-108.119313
SGE 8082E-25 F25496	0504519765	45	96W	24	SWNE	39.674492	-108.119335
SGE 8510E-24 F25 49	0504519768	45	96W	25	NWNE	39.674477	-108.119333
SGE 8084D-25 F25 49	0504519771	45	96W	24	SWSW	39.67438	-108.119822
SGE 8510E-24 F25 49	0504519762	45	96W	25	NWNE	39.674336	-108.119682
SGE 8084D-25 F25 49	0504519770	45	96W	24	NESE	39.674369	-108.119595
SGE 8084D-25 F25 49	0504519773	45	96W	24	NESE	39.67435	-108.119579
SGE 8082E-25 F25496	0504519756	45	96W	25	NWNE	39.674356	-108.119616
SGE 8087B-25 F25496	0504519775	45	96W	25	SENE	39.674425	-108.119437
SGE 8510E-24 F25496	0504519766	45	96W	25	SENE	39.674395	-108.119496
SGE 8510E-24 F25496	0504519763	45	96W	24	SWNE	39.674401	-108.119527
SGE 8510E-24 F25496	0504519758	45	96W	24	SWNE	39.674412	-108.119513
SGE 8510E-24 F25496	0504519776	45	96W	24	SWNE	39.674445	-108.119521
SGE 8510E-24 F25496	0504519772	45	96W	24	SWNE	39.674454	-108.119429

**ACCESSED BY-DIVIDE ROAD
 IN CASE OF EMERGENCY DIAL
 970-285-2615 OR 911**

Photo # 1060 Entrance to location - No Rig on location to P&A STORY GULCH UNIT #8510AX-25 F25 well during time off inspection

Photo # 1073 Location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC Story Gulch Unit/8506D-25 F25496 PAD

Location ID: 415182

Date: 01/15/2026



Photo # 1061 Location



Photo # 1066 Location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC Story Gulch Unit/8506D-25 F25496 PAD

Location ID: 415182

Date: 01/15/2026



Photo # 1072 Location



Photo # 1074 NE corner of location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC Story Gulch Unit/8506D-25 F25496 PAD

Location ID: 415182

Date: 01/15/2026



Photo # 1075 SE corner of location



Photo # 1076 SW corner of location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC Story Gulch Unit/8506D-25 F25496 PAD

Location ID: 415182

Date: 01/15/2026



Photo # 1077 NW corner of location



Photo # 1078 Tank battery lacks signage/not in compliance with CECMC rules