

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327



Photo 1 – 2-1H Well Site – Stained Soil

Photo 2 – Unused Wellhead parts

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327



Photo 3 – 2-1H Well Sign – Previous Operator’s Info still visible

Photo 4 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327



Photo 5 – 2-1H Pumping Unit

Photo 6 – 2-1H Wellhead

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327




Photo 7 – 2-3H Pumping Unit – Unused Rod

Photo 8 – 2-3H Wellhead – Stained Soil

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327




Photo 9 – 2-3H Wellhead – Stained Soil

Photo 10 – 2-3H Well Sign - Previous Operator's Info still visible. Unused Rod and Wellhead parts

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327



Photo 11 – 2-6H Gas Engine

Photo 12 – 2-6H Wellhead – Stained Soil

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327



Photo 13 – 2-6H Pumping Unit – Stained Soil



Photo 14 – 2-6H Well Sign - Previous Operator's Info still visible and unused Wellhead Parts

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327



Photo 15 – ECD

Photo 16 – Tank Battery

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327




Photo 17 – Tank Labels have faded

Photo 18 – Chemical Label has faded no longer visible

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327




Photo 19 – Tank Battery Signs – Previous Operator's Info still visible

Photo 20 – Tank Label has faded no longer visible

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327



Photo 21 – Tank Battery



Photo 22 – Heater Treaters

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327



Photo 23 – Heater Treaters and Compressor




Photo 24 – Unmarked Riser

Inspection Photos
Location Name: Loomis PAD
Location ID: 438327



Photo 25 – Unmarked Riser



Photo 26 – Label has faded no longer visible