

Inspection Photos

01/29/2026

Operator: QB Energy Operating LLC #10844

Location ID: 334665

Inspection Doc: 719200782

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334665



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334665



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334665



Photo 3: Photos showing an overview of wellheads at the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334665



Photo 3: Photos showing an overview of the northern and western interim areas, respectively. Limited inspection due to snow cover; interim areas appear to be progressing towards 1003 reclamation standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 334665



Photo 4: Photos showing an overview of the southwestern interim areas. Vegetation is sparse in places; additional reclamation/stabilization efforts may be required within this area in the future.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources