

Final Reclamation and Stormwater Inspection

January 29, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 328631

Well Name: GORDON RED V #10-15

Inspection Document #: 718601338

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GORDON RED V #10-15
Location ID: 328631



Photo 1. Looking east down the former access road from the well location. There appears to be limited desirable vegetation on the access road.



Photo 2. Looking west across the well location from the east side. List B noxious weed scotch thistle is present throughout the location. Scotch thistle rosettes were observed throughout the location.

Inspection Photos
Location Name: GORDON RED V #10-15
Location ID: 328631



Photo 3. Looking west from the wellbore area. The vegetation on the location consists primarily of undesirable weeds such as kochia and russian thistle. A limited amount of native forbs may be present on the location. The location is not reflective of the surrounding reference area.



Photo 4. Looking north from the wellbore. See photo 3 comments.

Inspection Photos
Location Name: GORDON RED V #10-15
Location ID: 328631



Photo 5. Looking south from the wellbore. See photo 3 comments.



Photo 6. Reference vegetation to the north of the well location. The reference area surrounding the well location consists primarily of cereal rye which may be considered an undesirable weed. Russian thistle and kochia are also present in the reference area.

