

# INSPECTION PHOTOS

**Well: GOLDEN EAGLE 33-01**

**API #: 05-071-08815**

**INSPECTION DOC #: 716301944**

**Operator: OGRIS OPERATING LLC 10758**

**Inspection date: 2/3/2026**

**County: Las Animas**

  
**OGRIS**  
OPERATING, LLC

719-497-0446

or 911

**GE 33-01 NE/NE**

**33-33S-67W**

**NAD 83**

**Lat. 37.133457**

**Long. 104.885004**

Network: Feb 3, 2026 at 1:07:01 PM MST

Local: Feb 3, 2026 at 1:07:01 PM MST

+37.133435, -104.885035

Las Animas County

PHOTO 2: WELL NAME IS NOT ACCURATE ON WELL SIGN AND THERE IS NO API# POSTED ON SIGN, POST ACCURATE SIGN AND API # WHEN SIGN IS REPLACED NEXT.



PHOTO 3: LOCATION.



PHOTO 4: WELLHEAD AND EQUIPMENT.



Network:Feb 3, 2026 at 1:08:53 PM MST  
Local:Feb 3, 2026 at 1:08:53 PM MST  
+37.133581,-104.885054  
Las Animas County

**PHOTO 5: USUSED EQUIPMENT STORED ON LOCATION (PRIME MOVER ENGINE SKID HAS NO ENGINE). REMOVE UNUSED EQUIPMENT PER RULE 606. CA DATE 3/3/2026.**