

# INSPECTION PHOTOS

**Well: GOLDEN EAGLE 33-07**

**API #: 05-071-09513**

**INSPECTION DOC #: 716301946**

**Operator: OGRIS OPERATING LLC 10758**

**Inspection date: 2/3/2026**

**County: Las Animas**



**OGRIS**  
OPERATING, LLC

719-497-0446  
or EMERGENCY 911

WDID 1912574  
PERMIT 71344

GOLDEN EAGLE 33-07  
API# 05-071-09513  
NE/SW 33-33S-67W  
NAD 83  
LAT. 37.131137  
LONG. -104.889993

**API# 05-071-09513**

Network:Feb 3, 2026 at 1:49:19 PM MST  
Local:Feb 3, 2026 at 1:49:19 PM MST  
+37.131234,-104.889940  
Las Animas County

PHOTO 2: WELL SIGN



PHOTO 3: LOCATION.



PHOTO 4: WELLHEAD AND EQUIPMENT.



**PHOTO 5: AREA OF IMPACTED SOIL AROUND WELLHEAD BOTH OILY STAINING AND WHITE CHALKY MINERAL BUILDUP FROM REPEATED WELL PACKING LEAKING. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. CA DATE 2-10-2026.**



PHOTO 6: OILY WASTE IN PRIME MOVER SKID DOES NOT APPEAR TO BE FROM LEAKING EQUIPMENT, IT APPEARS THAT THE OIL FROM THE ENGINE HAS BEEN DRAINED INTO SKID WITH NO WILDLIFE PROTECTION SCREEN OR NETTING. **STOP DRAINING ENGINE OIL INTO SKIDS WITH NO WILDLIFE PROTECTION, DRAIN OIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 2-4-2026.**