

Inspection Photos

01/29/2026

Operator: QB Energy Operating LLC #10844

Location ID: 324019

Inspection Doc: 719200790

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 324019



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 324019



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 324019



Photo 3: Photo showing old sign debris/trash with incorrect information. Removal is required; comply with Rule 606.d.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 324019



Photo 4: Photos showing an overview of the northern and southern interim areas, respectively. Interim areas passed interim reclamation requirements (inspection # 692402201).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources