


(SUBMIT IN TRIPLICATE)

Land Office **Colo. 93966**

Lease **South Douglas Creek**

Unit



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



103-05007

SUNDRY NOTICES AND REPORTS ON WELLS

| | |
|--|---|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | Subsequent Notice of Setting Casing X |
| NOTICE OF INTENTION TO ABANDON WELL | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 18, 1957

Well No. **1** is located **1648** ft. from **XX** line and **390** ft. from **E** line of sec. **16**
34 54 16 **74E** **R101W** **6ch**
South Douglas Creek (Twp.) **Rio Blanco** (Meridian) **Colorado**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **Unknown (Will be determined later)** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 460 ft. 36⁷/₈ casing. Set at 400' with 210 Sax Cement.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Pan American Petroleum Corporation**

Address **Engely, Colorado**

By **JH Parcasto**

Title **Field Superintendent**