

# Inspection Photos

01/29/2026

Operator: QB Energy Operating LLC #10844

Location ID: 323979

Inspection Doc: 719200794

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323979



**Photo 1:** Photos showing an overview of the location looking northeast and southwest, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323979



**Photo 2:** Photos showing an overview of the location looking southeast and north, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323979



**Photo 3:** Photo showing signage that is peeled/illegible and appears to be trash/debris. Removal is required; comply with Rule 606.d.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB Energy Operating LLC #10844

Location ID: 323979



**Photo 4:** Photos showing an overview of the southern and northern interim areas, respectively. Interim areas are progressing towards 1003 reclamation standards.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources