

Inspection Photos
Location Name: Jacobucci Jean 1
Location ID: 317872



Photo 1 Location.

Photo 2 Wellhead.

Inspection Photos
Location Name: Jacobucci Jean 1
Location ID: 317872



Photo 3 Well site sign.

Photo 4 Location.

Inspection Photos
Location Name: Jacobucci Jean 1
Location ID: 317872




Photo 5 Pump Jack horse head & walking beam have come off the samson post.

Photo 6 Pump Jack horse head & walking beam have come off the samson post.

Inspection Photos
Location Name: Jacobucci Jean 1
Location ID: 317872



Photo 7 Broken pitman equalizer.

Photo 8 Stained soil under the gas engine.

Inspection Photos
Location Name: Jacobucci Jean 1
Location ID: 317872




Photo 9 Stained soil under the gas engine.

Photo 10 Pump Jack horse head & walking beam have come off the samson post.