

Inspection Photos

February 3rd, 2026

Operator: Simcoe LLC

Location ID: 333662

Inspection Document #: 714003438

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Dekay A1, A3
Location ID: 333622

February 3, 2026
193° S



Photo 1. View of the active pad taken from the northern edge facing center.

Inspection Photos
Location Name: Dekay A1, A3
Location ID: 333622

February 3, 2026
219° SW



Photo 2. Weedy russian thistle debris observed on active pad.

Inspection Photos
Location Name: Dekay A1, A3
Location ID: 333622

February 3, 2026
41° NE



Photo 3. Location interim reclamation area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

February 3, 2026
162° S



Photo 4. No stormwater issues observed at the culvert along location access point.

