

Inspection Photos

February 3rd, 2026

Operator: Abundance Energy Services

Location ID: 325138

Inspection Document #: 714003427

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Herrera MVRD Gas Unit 1

Location ID: 325138

February 3, 2026
71° E



Photo 1. View of the active pad taken from the western edge facing center.



Inspection Photos

Location Name: Herrera MVRD Gas Unit 1

Location ID: 325138

February 3, 2026
192° S



Photo 2. Location access road.



Inspection Photos

Location Name: Herrera MVRD Gas Unit 1

Location ID: 325138



Photo 3. View of wellhead and location sign.



Inspection Photos

Location Name: Herrera MVRD Gas Unit 1

Location ID: 325138



Photo 4. Produced water tank secondary containment berm damage (highlighted with red arrow).