

# Inspection Photos

February 3rd, 2026

Operator: Abundance Energy Services

Location ID: 311891

Inspection Document #: 714003433

County: La Plata

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

February 3, 2026  
212° SW



**Photo 1.** View of the active pad taken from the northern edge facing center.



Inspection Photos  
Location Name: IGS Multiwell Pad  
Location ID: 311891

February 3, 2026  
344° N



**Photo 2.** View of weedy debris on the location cut slope.

February 3, 2026  
345° N



**Photo 3.** Location interim reclamation area.