

Inspection Photos

February 3rd, 2026

Operator: Abundance Energy Services

Location ID: 333357

Inspection Document #: 714003421

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

February 3, 2026
55° NE



Photo 1. View of the active pad taken from the southern edge facing center.

February 3, 2026
2° N



Photo 2. View of gully erosion forming in the NW corner of the disturbance.

February 3, 2026
211° SW



Photo 3. View of gully erosion that has formed in the NW corner of the pad. Gully erosion has formed a long channel running north to a stock pond. Current stormwater BMPs are lacking or insufficient.



February 3, 2026
78° E



Photo 4. View of wattles and old stakes on the northern edge of the pad.

February 3, 2026
166° S



Photo 5. View of interim reclamation vegetation.