

Inspection Photos

February 3rd, 2026

Operator: Abundance Energy Services

Location ID: 325116

Inspection Document #: 714003436

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: McElvain Tatum Unit 1

Location ID: 325116

February 3, 2026
247° SW



Photo 1. View of the active pad taken from the northern edge facing center.



Inspection Photos

Location Name: McElvain Tatum Unit 1

Location ID: 325116

February 3, 2026
234° SW



Photo 2. View of wellhead.



Inspection Photos

Location Name: McElvain Tatum Unit 1

Location ID: 325116

February 3, 2026
308° NW



Photo 3. Secondary containment walls have sunken in and is no longer sufficient.

