

Inspection Photos

February 3rd, 2026

Operator: Rim Operating Inc.

Location ID: 333802

Inspection Document #: 714003441

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

February 3, 2026
28° NE



Photo 1. View of the active pad taken from the southern edge facing center.

Inspection Photos

Location Name: Pikes Peak 1

Location ID: 333802

February 3, 2026
72° E



Photo 2. View of wellhead assembly.



February 3, 2026
20° N



Photo 3. View of produced water secondary containment berm which is insufficient.