

Inspection Photos

Location Name: 70 RANCH-LAURA-65N63W /20NWSW

Location #: 332409



Photo #1

70 Ranch-Laura 13-20 (123-22260) Wellsite

Shut-In | SI



Photo #2

70 Ranch-Laura 13-20 Wellsite

Shut-In | SI

Wellsite(s) entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: 70 RANCH-LAURA-65N63W /20NWSW

Location #: 332409



Photo #3

70 Ranch Laura 13-20, 14-20, 24-20, 34-20, CSW 20

Battery site

Inactive | Shut-down

Equipment Documented; Loc ID: 332409



Photo #4

70 Ranch Laura 13-20, 14-20, 24-20, 34-20, CSW 20

Battery site

Inactive | Shut-down

Battery entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources