

# Inspection Photos

Location Name: 70 RANCH LAURA-65N63W/20SWSE

Location #: 332433



**Photo #1**

**70 Ranch Laura 34-20 (123-22293) Wellsite**

**Shut-In | SI**



**Photo #2**

**70 Ranch Laura 34-20 Wellsite**

**Shut-In | SI**

*Wellsite(s) entrance*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: 70 RANCH LAURA-65N63W/20SWSE

Location #: 332433



**Photo #3**

**70 Ranch Laura 13-20, 14-20, 24-20, 34-20, CSW 20**

Battery site

**Inactive | Shut-down**

***Equipment Documented; Loc ID: 332409***



**Photo #4**

**70 Ranch Laura 13-20, 14-20, 24-20, 34-20, CSW 20**

Battery site

**Inactive | Shut-down**

***Battery entrance***



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources