



LEASE INSPECTION FORM

CONFIRMED BY FIELD INSPECTION

Operator CONOCO

Date 8/19/85

Lease Name & No. #56

Field MCCALLUM

Tank Battery No. N/A

County JACKSON

Location SE NW 2-9N-79W  
Legal Description

Type of Inspection Wellsite

Water Inflow \_\_\_\_\_ (Bbls. Per Day)

RESULTS OF INSPECTION

(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)  
Type of Tank

SKIM TANK FOUND INDICATIONS OF EARTHWORK ON A FAIRLY LEVEL AREA

FOUND 9 5/8" CASING STICKING 1 1/2' ABOVE GROUND

Pit No. 1 WITH SERREWED ON PLATE

COULDN'T UNSERREW PLATE TO SEE HOW DEEP PIPE WAS SET

Pit No. 2 \_\_\_\_\_

I BELIEVE THIS IS THE RIGHT WELL LOCATION

Pit No. 3 SUSPECT EITHER SFC CSG SET OR 9 5/8" BEING USED AS CONDUCTOR,

ALTHOUGH THAT'S RATHER SMALL

ADDITIONAL PITS \_\_\_\_\_

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety Conditions, Etc.)

TALKED W/ DAN SEELYE - PROD. FOREMAN - AND CONFIRMED 9 5/8" SFC

CSG SET TO 55-65' ON # 53, 54, 55, 56

RECOMMENDED ACTION (If Required) INCLUDE THIS IN REQUEST FOR INFO LETTER.

INSPECTOR ISK

Also #53, 54, 55